
105mm Operating instructions **COFFEE SCALE MANUAL** 1.Switch On/Off When the Power switch on, short press  $\begin{pmatrix} \emptyset \\ TARE \end{pmatrix}$  turn on scale. long press  $\begin{pmatrix} \emptyset \\ TARE \end{pmatrix}$  to turn off. 188:88° TIMER TARE -8.8.8.8 **2.Timer Button Function** 2.1 Short press (TIMER) to start/stop Timer רחח 148mm 2.2 Long press 2 seconds to clear timer -00:00 0.0 TIMER 2.3 One short and one long touch to get into auto mode (timer flashing), timer start counting when water start pouring in - 00:00' 0.0' (U) TARE 2.4 Short press twice (TIMER) to convert units. -00:08 TARE 0.0 封面 2



正面

The backlight will close when there is no operation within 30S and no weight change, the backlight will reopen when pressing or button operation. If there is no operation about 5 minutes and no weight change, it will automatically turn off.

## **A** Warning

- Do not put any hot object(over 55 degrees celsius) on the scale, unless use silicon mat.
- Please put the scale on hard & flat surface for accurate weighing.
- When overload, please take off the object immediately, or will damage the sensor.
- Do not weighing with charging cable on.
- Do not leave the object on scale for long time.
- Please charge the scale once a month when it's in idle.
- Not allow children to use it(with age under 12).
- Do not put it into water.
- Store the product in a dry, non-corrosive environment.
- Please contact us when you meet any problem.





